

FIRST RE-ESTABLISHMENT

GCDB 140600

Quarter corner common to Sections 6 and 7, Township 40 South, Range 3 West, W.M. $V = 18\frac{1}{2}^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch Galvanized iron pipe, 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1977
T40S R3W
6
¼S —
7

Original bearing trees recorded by S.W. Lackland in 1882 found as follows:

- Laurel, 32-inch diameter with rotted faces bears Record: $N8^\circ E$, 26.40 feet to rotted lower face.
- Easterly branch, 14-inch diameter of a double Madrone, containing reverse impression of scribe marks in upper and evidence of axe work in rotted lower face bears Record: $S19^\circ E$, 24.42 feet to scribed (reverse) face. Original stone not found.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Ponderosa Pine, 10-inch diameter bears $N7^\circ E$, 17.65 feet.
- Douglas Fir, 15-inch diameter bears $S79^\circ W$, 13.15 feet.

Corner lies approximately 1,300 feet North of road, 106 feet North of mining ditch and 20 feet West of ridge top C. N-S.

May 9, 1977
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor