

## FIRST RE-ESTABLISHMENT

GCDB 200640

Quarter corner common to Sections 5 and 6, Township 40 South, Range 3 West, W.M.  $V = 20^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch Galvanized iron pipe, 30 inches in the ground with a 2½-inch bronze disc marked:

JACKSON COUNTY 1977  
T40S R3W  
¼S  
6 | 5

An original bearing tree, recorded by S. Lackland in 1882, now a dead Black Oak, 7-inch diameter containing scribed "BT" in exposed and rotted face bears Record:  $S39^\circ E$ , 15.18 feet to scribed face.

- Stump hole found at record location of Northwest bearing tree.
- The original 14 x 10 x 7-inch Record: 15 x 14 x 10-inch stone marked "¼" found about 20 feet Easterly (downhill) from corner. (Deposit stone alongside corner).

I marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir, 14-inch diameter bears  $N83\frac{1}{2}^\circ E$ , 25.63 feet.
- Douglas Fir, 14-inch diameter bears  $N40^\circ W$ , 15.64 feet.

Corner lies 25 feet North of East-West ridge and about 650 feet West of jeep road crossing (same) ridge.

May 18, 1977  
B. Malotte  
R. Frost  
T. Newcomb, USFS - Witness  
J. Anderson, USFS - Witness

Approved by:  
Edward McGinty,  
County Surveyor