

FIRST RE-ESTABLISHMENT

GCDB 700540

Quarter corner common to Section 12, Township 40 South, Range 3 West, and Section 7, Township 40 South, Range 2 West, W.M. $V = 20\frac{1}{2}^\circ$

Found tipped over, the 12 x 8 x 5-inch stone, Record: 15 x 10 x 9-inch marked "¼" by S. Lackland in 1882.

I replaced said stone with a 1 x 36-inch Galvanized iron pipe, set 30 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1977
T40S
¼S
12 | 7
R3W R2W

- The single remaining bearing tree recorded by Lackland now a Laurel snag, 8-inch diameter, with axed and/or rotted faces bears Record: $N2^\circ E$, 7.92 feet to estimated upper face.
- Stump hole found at record location of SW BT.

I deposited original stone alongside a a memorial to corner, mark the following trees CS BT and took measurements to center of trees at lower blaze:

- Black Oak, 8-inch diameter bears $S52\frac{1}{2}^\circ E$, 37.37 feet.
- Douglas Fir, 7-inch diameter bears $S54\frac{1}{2}^\circ W$, 37.43 feet.

Corner lies on steep (60%) North slope.

West bearing dry stream bed bears North, 140 feet.

January 24, 1977
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor