

FIRST RE-ESTABLISHMENT

GCDB 540600

Quarter corner common to Sections 2 and 11, Township 41 South, Range 2 West, W.M.

Monument set by the GLO in 1916, destroyed by skid road.

From the following evidence, set at the true position, a 1 x 30-inch Galvanized iron pipe, with a 2½-inch diameter brass cap, exposed 6 inches, marked:

JACKSON COUNTY SURVEYOR
T41S R2W
S2
¼S —
S11
2007

Single remaining original bearing tree recorded by Fred W. Rodolf of the GLO in 1916, a Shasta fir, now 39-inch diameter with healed single blaze bears Record: S59½°W, 17.2 feet to center at base.

Marked new bearing trees "CS" "BT" and took measurements to center at lower blaze:

- Shasta fir 20-inch diameter bears S61°E, 51.8 feet.
- Shasta fir 31-inch diameter bears N33½°W, 108.1 feet.

Corner lies in skid road approximately 200 feet easterly from graveled road.

November 26, 2007

H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. - 249
V. - 16°